CONTRACTOR SITE AND SAFETY FILE AUDIT / INSPECTION SHEET

СО	NTRACTOR DETAILS	GENERAL SITE DETAILS		
Contractor Name	Dynamic Options	Safety co-ordinator	Adri van der Merwe	
Site Supervisor	Trudi van der Merwe	Contact No.	011 315 4107 / 064 681 7578	
Contact No.	084 597 2138	Audit site address	Dynamic Options Workshop Modderfontein Industrial Complex.	
Company Address	Unit 17, 18 & 19 Gallagher Business Park, Gallagher Road, Midrand	Project details	Steel Fabrication & Engineering for 2019 Nitrates shutdown.	
Main business function	Steel Engineering & fabrication	Date of Audit/ Inspection	24 April 2019	
Postal Address	Postnet Suite 190 Private Bag 10010 Edenvale 1610	e-Mail Address	info@dynamico.co.za	
Number of employees	Nitrates Shutdown 2019	e-Mail Address	trudie@dynamico.co.za	



AUDITER DETAILS				
Company Name	AOCS			
Auditor Name	A Fouché			
Contact Details	082 455 2819			
e-Mail Address	andre@aocs.co.za			

Y =1 N=0

ITEM	Y/N	Number	Expiry Date	Cert number / Company
Workman's compensation (LGS)	1	RMA - D0099	31-Mar-20	RMA Certificate number 20193D00995 (28 Employees)
Public liability > R 1 000 000	1	OT 169890	30-Apr-19	Outsurance (R1 982 000.00)

C: Individual section results

Section	Y	N	N/A	% achieved for section
A: PHYSICAL AUDIT INSPECTION				
A1: SITE DEMARCATION AND BARRICADING/ CHANGE ROOMS	6	0	0	100.0
A2: HOUSEKEEPING & WALKWAYS	12	0	1	100.0
A3: SECURITY, FIRE FIGHTING, EMERGENCY & GENERAL SAFETY			+ +	
Security	0	1	1	0.0
Fire Fighting	7	0	0	100.0
Emergency Procedures and General Safety	3	0	1	100.0
A4: HAZARDOUS MATERIAL/SUBSTANCES / EXPLOSIVES AREAS	9	1	0	90.0
A5: SCAFFOLDING AND LADDERS	15	0	11	100.0
A6: EQUIPMENT AND GENERAL SAFETY				
Portable Electrical Equipment	5	0	1	100.0
Electrical (General)	11	0	2	100.0
Lifting Equipment	5	0	0	100.0
Cutting and Welding	5	0	0	100.0
General Tools and equipment	6	0	2	100.0
B: SHE MANAGEMENT AUDIT / INSPECTION			+ +	
Safety Management	15	1	2	93.8
Appointments	27	0	13	100.0
Environmental Management	2	0	0	100.0
Health & Ergonomics	3	2	1	60.0
First Aid/Incidents	9	0	0	100.0
Vehicles	10	0	5	90.9
Risk Assessment Inspection	16	2	2	88.9
Personal Protective Equipment (PPE)	3	1	0	75.0

| C: SITE AUDIT RESULT | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 | 169 |

D: COMMENTS / RECOMMENDATIONS

Refer to the comments next to the audit findings for suggested corrective actions.

Total amount of serious finding raised on "Gate Keeper" requirements = 5

Contractor: <u>T v d Merwe</u>

Name

Signature

Auditor: <u>A Fouché</u>

Name

Signature

24 April 2019 Date